



Complete Right Angle Rotary Polisher Assembly



Wiring Diagram



Correct Resting Position



Index Key

No. Part # Description

1 89371 Spindle	17 89386 Circlip	33 89422 Magnetic Ring
2 89437 Screw (4)	18 50677 Bearing	34 89423 "E" Ring
3 89438 Washer (4)	19 89387 Bearing Cover	35 89433 Handle Cover
4 89439 Gear Box Cover	20 89388 Armature	36 89450 Screw (4)
5 89452 Bearing	21 02649 Bearing	37 89426 Speed Controller Switch
6 89375 Bearing Cover	22 89447 Bearing Bush	38 89451 Screw
7 89440 Washer (6)	23 89391 Baffle	39 89427 Cord Clamp
8 89257 Screw (6)	24 89392 Screw (2)	40 89446 Screw (2)
9 89377 Gear	25 89393 Stator	41 89444 Cord Sleeve
10 89378 Bearing	26 89394 Ring Terminal (2)	42 89445 Cord
11 89441 Side Handle	27 89395 Label	43 89436 Handle
12 89442 Screw (4)	28 89448 Housing	44 89430 Rubber Cap (3)
13 89382 Spindle Lock	29 89397 Label	45 89431 Spanner
14 89383 Spindle Lock Spring (4)	30 89398 Brush Holder (2)	46 89449 Magnetic Ring Cover
15 89384 Snap Ring	31 89399 Carbon Brush (2)	47 89434 Button
16 89443 Gear Box	32 89421 Brush Holder Cap (2)	48 89435 Spring

Definitions of Label Symbols

Symbol	Description
A	amperes
Hz	hertz
□	Class II Construction