



**SMITH-COOPER.**  
INTERNATIONAL

### **Legacy Smith-Cooper Part Number Changes**

The merger of Anvil International and Smith-Cooper International has created the opportunity to merge to a singular part numbering system. The singular part numbering system has created new 10 digit item numbers that are replacing the legacy Smith-Cooper item codes. Please note the following regarding this change:

- The file named “Legacy Smith-Cooper New Part Numbering” has a full cross reference of previous Smith-Cooper products including all brands such as FPPI and Sharpe.
- No legacy Anvil part numbers are changing.
- UPC’s for Legacy Smith-Cooper did not change.
- All other data related information for legacy Smith-Cooper parts did not change.
- US Price files for all Anvil Smith-Cooper products can be found at <https://www.anvilintl.com/price-sheets/us-price-sheets>

Please visit [www.anvilintl.com/company/merger](http://www.anvilintl.com/company/merger) or contact your local sales representative for more information regarding this change.

#### **ANVIL INTERNATIONAL**

2 Holland Way, Exeter, NH 03833  
603-418-2800 P 603-418-2833 F  
[www.anvilintl.com](http://www.anvilintl.com)

#### **SMITH-COOPER INTERNATIONAL**

2867 Vail Avenue, Commerce, CA 90040  
800-766-0076 P 323-890-4456 F  
[www.smithcooper.com](http://www.smithcooper.com)

#### **POWER AND PROCESS OFFICE**

160 Frenchtown Road, North Kingstown, RI 02852  
401-886-3000 P 401-886-3010 F  
401-533-6896 EMERGENCY  
[www.anvileps.com](http://www.anvileps.com)