



This report provided free of charge by:

Good Life Motors
301 11th Ave N, Nampa, ID 83687
208-203-8291

★ 4.5 out of 5.0

10 Verified Reviews

♥ 6

Customer Favorites



Vehicle History Report™

US \$39.99

2009 CHEVROLET SILVERADO K1500

VIN: 1GCEK19049E154297
4 DOOR EXTENDED CAB PICKUP
5.3L V8 F OHV 16V
FLEX FUEL
REAR WHEEL DRIVE W/ 4X4



No accidents or damage reported to CARFAX



At least 1 open recall



4 Service history records



5 Detailed records available



34,955 Last reported odometer reading



This CARFAX Report Provided by:

Good Life Motors

★ 4.5 / 5.0 10 Verified Reviews

♥ 6 Customer Favorites

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/22/21 at 4:04:23 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Title History

CARFAX guarantees the information in this section

Summary

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed
No Problem

Not Actual Mileage | Exceeds Mechanical Limits



Guaranteed
No Problem



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.

[Register](#) | [View Terms](#) | [View Certificate](#)



Additional History

Not all accidents / issues are reported to CARFAX

Summary

Total Loss

No total loss reported to CARFAX.



No Issues Reported

Structural Damage

No structural damage reported to CARFAX.



No Issues Reported

Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues Reported

Odometer Check

No indication of an odometer rollback.



No Issues Indicated

Accident / Damage

No accidents or damage reported to CARFAX.



No Issues Reported

Manufacturer Recall

At least 1 manufacturer recall requires service. Check for open recalls or schedule dealer service on GM vehicles at [recalls.gm.com](https://www.gm.com/recalls).

Recall Reported

Basic Warranty

[Original warranty](#) estimated to have expired.

Warranty Expired

Date	Mileage	Source	Comments
08/04/2015	19,112	Bob's Automotive, Inc. Ridgefield, WA 360-887-8351 bobsautoinc.com 3 Customer Favorites	Vehicle serviced - A/C condenser replaced - Oil and filter changed - A/C system serviced - A/C refrigerant recharged - Fluids checked
02/09/2017	22,217	Alan Webb Chevrolet Mazda Vancouver, WA 360-574-1131 alanwebbautogroup.com 4.5 / 5.0 175 Verified Reviews 3,410 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Electrical system checked - Tire pressure sensor replaced - Transmission computer/module replaced
09/09/2020	32,751	Alan Webb Chevrolet Vancouver, WA 360-450-0021 https://alanwebbchevy.com 4.5 / 5.0 114 Verified Reviews 2 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Alignment performed - Ball joint(s) replaced - Front wheel bearing(s)/hub(s) replaced
02/05/2021		General Motors	Manufacturer Safety recall issued - NHTSA #21V052 - Recall #N212328780 - FRONT PASSENGER AIRBAG TAKATA INFLATOR - PRIORITY - GROUP 8 - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall. - Learn more about this recall
<p>Description: TK Holdings Inc. (Takata) has decided that a defect which relates to motor vehicle safety exists in the passenger-side frontal airbag inflators installed as original equipment in certain 2007 to 2014 model year Cadillac Escalade, Escalade ESV, and Escalade EXT vehicles; certain Chevrolet Avalanche, Silverado 1500, Silverado 2500/3500, Suburban, and Tahoe vehicles; and certain GMC Sierra 1500, Sierra 2500/3500, Yukon, and Yukon XL vehicles. The determination was made that the propellant in these inflators may degrade after long-term exposure to high humidity and temperature cycling, which could cause the inflator to rupture during a deployment.</p> <p>An inator rupture may cause metal fragments to pass through the airbag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.</p> <p>Remedy: Dealers will replace the passenger-side frontal airbag inflator.</p>			
10/28/2021	34,955	Quality Alignment And Mechanical Nampa, ID 208-467-6025 4.9 / 5.0 29 Verified Reviews 20 Customer Favorites	Vehicle serviced

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved.
11/22/21 4:04:23 PM (CST)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2009 CHEVROLET SILVERADO vehicle (VIN: 1GCEK19049E154297), which is based on information supplied to CARFAX and available as of 11/22/21 at 5:04 PM (EST).

Customer Signature

Date

Dealer Signature

Date