



SERVICE PARTS LIST

BULLETIN NO.
PN0006611

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
M18™ <i>HOT/SHOT</i> Jump Starter				Mar. 2025
CATALOG NO.	3841-20	SERIAL NUMBER	WIRING INSTRUCTION	
		R47A		

EXAMPLE:

00	0
0	0

Component Parts (Small #)
Are Included When Ordering
The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
	8	Screw 3x8	(12)
19		Cable Storage Post Left	(1)
20		Clamp Storage Post Left	(1)
21		Screw 3x12	(2)
22		Positioning Block	(2)
23		Handle Cover Left	(1)
26		Handle	(1)
31		Clamp Storage Post Right	(1)
32		Handle Cover Right	(1)
33		Cable Storage Post Right	(1)
34	31-15-1585	USB-C Cover	(1)
37	12-20-1102	Service Nameplate (not shown)	(1)
60	14-34-1080	Handle Kit	(1)
61	14-02-0055	Clamp and Cable Post Kit	(1)

FIG. 37 NOTES

A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.