



Millennium ESCU/EDCD/NetDCD

---

Firmware update version 6D build 5 Release Notes

1. Software Bugs Addressed

- Door Forced Alarm time interval for Relay 2 bug fix – Relay 2 returns to initial state after the configured time interval, not after Door Forced Alarm reset
- Communication protocol optimization for ECU/ECD boards – not all floors were configured correctly in case of low quality communication between ESCU/NETDcd and ECU boards
- Time difference related bug with Enterprise/Expert systems – in Enterprise/Expert the day change can be processed not correctly if the board has different time compare with the host computer