



This data was originally accessed on 2026-03-13 17:40:12.895 EDT at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)

VIN SPECIFICATION

Model Year		2017
Make		Polaris
Model		Slingshot
Manufacturer		Polaris Ind, Inc.
Production Seq. Number		121560
Engine Type		L4, 2384 cc
Fuel Type		Gasoline
Engine Code		3
Vehicle Type		Motorcycle
Motorcycles Type		3-Wheels
Country		UNITED STATES
Assy. Plant		Huntsville, AL
GVWR Class		Class A: 0-3,000 lb
Check Digit		3
Mobile6 Class.		MC
AAIA		243662
AAIA_ENGINE		20890
AAIA_LEGACY		
AAIA_TRANSMISSION		2340
AAIA_VehicleID		243662
AAIA_EngineConfigID		20890
AAIA_TransmissionID		2340
AAIA_BodyStyleConfigID		108
AAIA_BrakeConfigID		19
AAIA_DriveTypeID		4



This data was originally accessed on 2026-03-13 17:40:12.895 EDT at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)

AAIA_SpringTypeConfigID  15



This data was originally accessed on 2026-03-13 17:40:12.895 EDT at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)

MULTI-STATE VEHICLE HISTORY REPORT

CONDITION HISTORY		
Brand Category	NMVTIS Search Result	
Total Loss		No Title Brand found by Cyclechex.com
Salvage		No Title Brand found by Cyclechex.com
Disclosed Damage		No Title Brand found by Cyclechex.com
Bond		No Title Brand found by Cyclechex.com
Flood		No Title Brand found by Cyclechex.com
Cars/Cash for Clunkers		No Title Brand found by Cyclechex.com
Gray Market		No Title Brand found by Cyclechex.com
Junk		No Title Brand found by Cyclechex.com
Manufacturer Brand		No Title Brand found by Cyclechex.com
New/Re-Issued VIN		No Title Brand found by Cyclechex.com
Odometer		No Title Brand found by Cyclechex.com
Rebuilt/Repaired/Reconstructed		No Title Brand found by Cyclechex.com
Dismantled		No Title Brand found by Cyclechex.com
Rental/Taxi/Police		No Title Brand found by Cyclechex.com
Agricultural/Logging Vehicle		No Title Brand found by Cyclechex.com
Title Copy		No Title Brand found by Cyclechex.com
Antique/Classic		No Title Brand found by Cyclechex.com
Undisclosed Lien		No Title Brand found by Cyclechex.com

TITLE HISTORY				
State	Status	VIN	Issue Date	Odometer
Mississippi	Current	57XAASFA3H8121560	05/21/2018	405 Miles

No historical title records for this vehicle.

JUNK AND SALVAGE INFORMATION

No Junk/Salvage Reportings Found

RECALL DATA FROM NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION (NHTSA)

[Click here](#) to check for any unrepaired recalls associated with your motorcycle. Have your VIN available.

Report Received Date: 15/08/2018

Component: SEAT BELTS:FRONT:RETRACTOR

Manufacturer: Polaris Industries, Inc.

Summary: Polaris Industries, Inc. (Polaris) is recalling certain 2017-2019 Polaris Slingshot S, Slingshot SL, Slingshot GT LE, and Slingshot SLR motorcycles. In the event of a crash, the seatbelt retractor on the side opposite of the impact may separate, preventing the seatbelt from locking.

Remedy: Polaris will notify owners, and dealers will install a kit that prevents the retractor from separating in the event of a crash, free of charge. The recall began August 28, 2018. Owners may contact Polaris customer service at 1-855-863-2284. Polaris' number for this recall is T-18-03.

Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



This data was originally accessed on 2026-03-13 17:40:12.895 EDT at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)

Report Received Date: 16/05/2018
Component: SERVICE BRAKES, HYDRAULIC:PEDALS AND LINKAGES
Manufacturer: Polaris Industries, Inc.
Summary: Polaris Industries, Inc. (Polaris) is recalling certain 2017-2018 Polaris Slingshot, Slingshot SL, Slingshot SLR, Slingshot SL Icon, and Slingshot GT LE motorcycles. The brake pedals may have been incorrectly installed, allowing the brake pedal to separate from the brake master cylinder.
Remedy: Polaris will notify owners, and dealers will inspect the engagement of the brake pedal retaining clip and reassemble it if necessary, free of charge. The recall began on June 5, 2018. Owners may contact Polaris customer service at 1-855-863-2284. Polaris' number for this recall is T-18-02.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .
Report Received Date: 18/10/2019
Component: ELECTRICAL SYSTEM:WIRING:FUSES AND CIRCUIT BREAKERS
Manufacturer: Polaris Inc.
Summary: Polaris Inc. (Polaris) is recalling certain 2015-2019 Slingshot motorcycles. Excessive electrical current may damage the battery fuse holder terminals.
Remedy: Polaris will notify owners, and dealers will inspect the battery fuse block terminals and relocate the 50 amp chassis fuse, free of charge. The recall began October 24, 2019. Owners may contact Polaris customer service at 1-855-863-2284. Polaris's number for this recall is T-19-01.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .
Report Received Date: 19/10/2016
Component: POWER TRAIN:DRIVELINE
Manufacturer: Polaris Industries, Inc.
Summary: Polaris Industries, Inc. (Polaris) is recalling certain model year 2015-2017 Slingshot motorcycles manufactured March 4, 2014, to September 7, 2016. The affected vehicles may have been manufactured with a swing arm that has insufficient strength.
Remedy: Polaris will notify owners, and dealers will inspect, and repair or replace the swing arm, as necessary, free of charge. The recall began December 2016. Owners may contact Polaris customer service at 1-855-863-2284. Polaris' number for this recall is T-16-06.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .
Report Received Date: 18/10/2016
Component: FUEL SYSTEM, GASOLINE:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS
Manufacturer: Polaris Industries, Inc.
Summary: Polaris Industries, Inc. (Polaris) is recalling certain model year 2015-2017 Slingshot motorcycles manufactured March 4, 2014, to October 7, 2016. The affected vehicles may have insufficient clearance between the fuel line and the hood structure.
Remedy: Polaris will notify owners, and dealers will replace the engine fuel line, and inspect the retention clips to reduce the risk of interference, free of charge. The recall began December 2016. Owners may contact Polaris customer service at 1-855-863-2284. Polaris' number for this recall is T-16-03.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .
Report Received Date: 01/06/2017
Component: SERVICE BRAKES, HYDRAULIC:ANTILOCK/TRACTION CONTROL/ELECTRONIC LIMITED SLIP:WHEEL SPEED SENSOR/TONE RING
Manufacturer: Polaris Industries, Inc.
Summary: Polaris Industries, Inc. (Polaris) is recalling certain 2015-2017 Slingshot vehicles. The affected



This data was originally accessed on 2026-03-13 17:40:12.895 EDT at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)

vehicles previously had their rear swingarms replaced during the remedy of NHTSA recall number 16V-255. The replacement swingarms may have been installed without the sealing grommets installed, potentially resulting in road debris contaminating the rear wheel speed sensor.
Remedy: Polaris will notify owners, and dealers will inspect the swingarms for missing grommets, installing them as necessary, free of charge. The recall began June 13, 2017. Owners may contact Polaris customer service at 1-888-704-5290. Polaris' number for this recall is T-17-04.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .
Report Received Date: 26/03/2018
Component: SEATS
Manufacturer: Polaris Industries, Inc.
Summary: Polaris Industries, Inc. (Polaris) is recalling all 2015-2018 Polaris Slingshot motorcycles. The driver-seat and passenger-seat seat belt and seat back anchoring bracket may have been improperly welded. Additionally, differences in the seat assembly may prevent proper latching of the seat slider, allowing the driver's seat to move unexpectedly.
Remedy: Polaris will notify owners, and dealers will inspect the seat belt bracket and seat back welds, and the seat slider latching function. If the weld is missing or incomplete, or if the slider doesn't latch properly, the seat bases will be replaced, free of charge. The recall began on April 16, 2018. Owners may contact Polaris customer service at 1-855-863-2284. Polaris' number for this recall is T-18-01.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .
Report Received Date: 10/03/2017
Component: STEERING
Manufacturer: Polaris Industries, Inc.
Summary: Polaris Industries, Inc. (Polaris) is recalling certain 2017 Slingshot, Slingshot SL, and Slingshot SLR vehicles. Three of the bolted connections between the steering and the front suspension may have been insufficiently tightened, possibly resulting in a reduction of steering and/or front suspension performance.
Remedy: Polaris will notify owners, and dealers will replace the affected nuts and bolts, tightening them correctly, free of charge. The recall began on March 23, 2017. Owners may contact Polaris customer service at 1-855-863-2284. Polaris' number for this recall is T-17-01.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .
Report Received Date: 18/10/2016
Component: SERVICE BRAKES, HYDRAULIC
Manufacturer: Polaris Industries, Inc.
Summary: Polaris Industries, Inc. (Polaris) is recalling certain model year 2016-2017 Slingshot motorcycles manufactured December 28, 2015, to April 27, 2016. The brake pressure switch may have been over tightened in the affected motorcycles.
Remedy: Polaris will notify owners, and dealers will install new brake pressure switch seals, free of charge. The recall began December 2016. Owners may contact Polaris customer service at 1-855-863-2284. Polaris' number for this recall is T-16-02.
Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov .

INSURANCE INFORMATION

Occurrence	Reporting Entity	Date of Insurance Claim
------------	------------------	-------------------------

No Total Loss Reportings Found



This data was originally accessed on 2026-03-13 17:40:12.895 EDT at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)

LIEN INFORMATION	
Entity Title	Date
There are no liens reported for this vehicle.	

Lien data does not include information on all motor vehicles in the United States because not all lienholders provide information to the source of this lien data.

DETAILS			
Standard Data			
body-type	Street	check-digit	H
country	United States	engine-type	2384 disp 4 cyls
identification	57XAASFA3H8121560	make	Polaris
model	Slingshot	model-year	2017
production-seq-number	121560	vehicle-class	Street

DISCLAIMER

NMVTIS Consumer Access Product Disclaimer

The National Motor Vehicle Title Information System (NMVTIS) is an electronic system that contains information on certain automobiles titled in the United States. NMVTIS is intended to serve as a reliable source of title and [brand](#) history for automobiles, but it does not contain detailed information regarding a vehicle's repair history.

All states, insurance companies, and junk and salvage yards are required by federal law to regularly report information to NMVTIS. However, NMVTIS does not contain information on all motor vehicles in the United States because [some states](#) are not yet providing their vehicle data to the system. Currently, the data provided to NMVTIS by states is provided in a variety of time frames; while some states report and update NMVTIS data in "real-time" (as title transactions occur), other states send updates less frequently, such as once every 24 hours or within a period of days.

Information on previous, significant vehicle damage may not be included in the system if the vehicle was never determined by an insurance company (or other appropriate entity) to be a "total loss" or branded by a state titling agency. Conversely, an insurance carrier may be required to report a "total loss" even if the vehicle's titling-state has not determined the vehicle to be "salvage" or "junk."

A vehicle history report is NOT a substitute for an independent vehicle inspection. Before making a decision to purchase a vehicle, consumers are **strongly encouraged to also obtain an independent vehicle inspection** to ensure the vehicle does not have hidden damage. The [Approved NMVTIS Data Providers](#) (look for the NMVTIS logo) can include vehicle condition data from sources other than NMVTIS.

NMVTIS data **INCLUDES** (as available by those entities required to report to the System):

- Information from [participating](#) state motor vehicle titling agencies.
- Information on automobiles, buses, trucks, motorcycles, recreational vehicles, motor homes, and tractors. NMVTIS may not currently include commercial vehicles if those vehicles are not



This data was originally accessed on 2026-03-13 17:40:12.895 EDT at which time it was current with the National Motor Vehicle Title Information System (NMVTIS)

included in a state's primary database for title records (in some states, those vehicles are managed by a separate state agency), although these records may be added at a later time. Information on "brands" applied to vehicles provided by participating state motor vehicle titling agencies. Brand types and definitions vary by state, but may provide useful information about the condition or prior use of the vehicle.

Most recent odometer reading in the state's title record.

Information from insurance companies, and auto recyclers, including junk and salvage yards, that is required by law to be reported to the system, beginning March 31, 2009. This information will include if the vehicle was determined to be a "total loss" by an insurance carrier.

Information from junk and salvage yards receiving a "cash for clunker" vehicle traded-in under the Consumer Assistance to Recycle and Save Act of 2009 (CARS) Program.

Consumers are advised to visit vehiclehistory.bja.ojp.gov for details on how to interpret the information in the system and understand the meaning of various labels applied to vehicles by the participating state motor vehicle titling agencies.

ADD Consumer Access Disclaimer

Auto Data Direct, Inc. is a "read-only portal" of data stored in the NMVTIS databases. Data is passed directly from AAMVA to the client through the ADD interface, which has been tested and approved by AAMVA. ADD does not enter the information found on a NMVTIS record, nor is it responsible for the accuracy or verification of the information found therein. The motor vehicle records accessed by ADD clients are recorded by participating states and are current with those entities at the time of access through the ADD portal. Auto Data Direct is an Approved NMVTIS Data Provider.