USEDBIKESDIRECT

Polaris	slingshot	2023	157423
	0111133011101		

Service Items	Pass	Fail
Oil / Filter change		1
Vehicle Detailed		
Tag "Certified"		
Tag "As Is"		

Chain / Sprockets	Pass	Fail
Chain Condition		
Sprocket Condition		
Belt Drive condition	6	
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens		
Running Light		
Brake Light	/	

License Plate	Pass	Fail
LP Bracket		
License Plate Light	/	

Mirrors	Pass	Fail
Mirrors	/	

Cables / Controls / Levers	Pass	Fail
Throttle Operation		
Clutch Cable Operation		
All Levers Operation		

Brakes	Pass	Fail
Front Pads		
Front Master Cylinder		
Front Brake Lines		
Front Rotors		
Rear Brake Pads		
Rear Master Cylinder		
Rear Brake Lines		
Rear Rotors		

Battery / Electrical System	Pass	Fail
Replace Battery		
Regulator Rectifier	/	

Headlight	Pass	Fail
Head Light Lens		
High Beam Bulb		
Low Beam Bulb		
Headlight Aim	/	

Turn Signals	Pass	Fail
Turn Signal Operation	/	

Dashes / Gauges	Pass	Fail
Speedometer / Odometer		
Tachometer	/	
Indicator / Backlights	/	

Horns & Switches	Pass	Fail
Horn Operation		
Stop Switch Operation		7
Safety Switch Operation		

Handlebars and Grips	Pass	Fail
Handlebar Operation		Ve
Grips Operation		- made

Wheels / Tires	Pass	Fail
Front Wheel		V Sale
Front Wheel Bearings		
Front tire	V .	
Rear Wheel		
Rear Tire		
Rear Wheel Bearings	/	5/

Steering / Alignment	Pass	Fail
Headset Bearings		
Steering Operation		

Suspension	Pass	Fail
Fork Seals		
Fork Legs	\	
Rear Suspension	/	

Fuel System	Pass	Fail
Fuel Tank		
Carbs / Injectors		

Exhaust System	Pass	Fail
Exhaust Operation		

Cooling System	Pass	Fail
Radiatior operation		COMP
Fan Operation		
Hoses, Water Pump, System	/	

Test Ride Notes and Vehicle Information

The right side has 2 small scratches above the tail light. The right side also has scuffs below the mirror.