USEDBIKESDIRECT

Make: polaris **Model:** slingshot sl **Year:** 2024

Stock #: 163864 **Mileage:** 3668

8 Mile Test Ride	Completed
Complete 8 mile test ride	☑

20 Minute Idle	Completed
Complete 20 minute idle	☑

Service Items	Pass	Fail
Oil / Filter Change	☑	☐
Vehicle Detailed	☑	☐
Tag "Certified"	☑	☐
Tag "As Is"	☑	☐

Chain / Sprockets	Pass	Fail
Chain Condition	☐	☐
Chain Adjuster Inspection	☐	☐
Sprocket Condition	☐	☐
Belt Drive Condition	☑	☐
Shaft Drive Condition	☐	☐

Tail Light	Pass	Fail
Lens	☑	☐
Running Light	☑	☐
Brake Light - Front Lever	☐	☐
Brake Light - Rear Pedal	☑	☐

License Plate	Pass	Fail
LP Bracket	☑	☐
License Plate Light	☑	☐

Mirrors	Pass	Fail
Mirrors	☑	☐

Handlebars and Grips	Pass	Fail
Handlebar Operation	☐	☐
Grips Operation	☐	☐

Battery / Electrical System		Pass	Fail
Replace Battery		☑	☐
Regulator Rectifier		☑	☐
Charging System Test	14.5 V	☑	☐

Headlight	Pass	Fail
Head Light Lens	☑	☐
High Beam Bulb	☑	☐
Low Beam Bulb	☑	☐
Headlight Aim	☑	☐

Turn Signals	Pass	Fail
Turn Signal Operation	☑	☐
Turn Signal Condition	☑	☐

Dashes / Gauges	Pass	Fail
Speedometer / Odometer	☑	☐
Tachometer	☑	☐
Indicator / Backlights	☑	☐

Horns & Switches	Pass	Fail
Horn Operation	☑	☐
Stop Switch Operation	☑	☐
Safety Switch Operation	☐	☐

Fuel System	Pass	Fail
Fuel Tank - Inside	☑	☐
Fuel Tank - Outside	☑	☐
Carbs / Injectors	☑	☐

Inspection (continued)

Stock #: 163864 **Mileage:** 3668

Cables / Controls / Levers	Pass	Fail
Throttle Operation	☑	☐
Throttle Cable Free Play	☑	☐
Clutch Cable Operation	☐	☐
Clutch Cable Free Play	☐	☐
Cable Routing	☑	☐
All Levers Operation	☐	☐
Quick Shifter (if equipped)	☐	☐

Brakes			Pass	Fail
Front Pads	90	% life	☑	☐
Front Master Cylinder			☑	☐
Front Brake Lines			☑	☐
Front Rotors			☑	☐
Rear Brake Pads	90	% life	☑	☐
Rear Master Cylinder			☑	☐
Rear Brake Lines			☑	☐
Rear Rotor			☑	☐

Suspension	Pass	Fail
Fork Seals	☐	☐
Fork Dust Covers	☐	☐
Fork Legs	☐	☐
Rear Suspension	☑	☐

Wheels / Tires			Pass	Fail
Front Wheel			☑	☐
Front Wheel Bearings			☑	☐
Front Tire	3123	date code	☑	☐
Front Tread Depth	9	/32"	☑	☐
Rear Wheel			☑	☐
Rear Tire	3123	date code	☑	☐
Rear Tread Depth	10	/32"	☑	☐
Rear Wheel Bearing Play			☑	☐

Steering / Alignment	Pass	Fail
Headset Bearings	☐	☐
Steering Operation	☑	☐
Front Steering Alignment	☑	☐

Exhaust System	Pass	Fail
Exhaust Operation	☑	☐

Cooling System	Pass	Fail
Radiator Operation	☑	☐
Fan Operation	☑	☐
Hoses, Water Pump, System	☑	☐

Test Ride Notes and Vehicle Information
took the unit for a test dive and it preformed as it should

Technician: Jacob Wilkerson **Date:** 10/13/2026