USEDBIKESDIRECT

Yamaha	YZF-R1	2016	001963

Service Items	Pass	Fail
Oil / Filter change	Y ,	1
Vehicle Detailed		
Tag "Certified"		
Tag "As Is"		

Chain / Sprockets	Pass	Fail
Chain Condition		
Sprocket Condition		
Belt Drive condition	4	
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens		
Running Light		
Brake Light		

License Plate	Pass	Fail
LP Bracket		
License Plate Light		

Mirrors	Pass	Fail
Mirrors		

Cables / Controls / Levers	Pass	Fail
Throttle Operation		
Clutch Cable Operation		
All Levers Operation		

Brakes	Pass	Fail
Front Pads		
Front Master Cylinder		
Front Brake Lines		\
Front Rotors		
Rear Brake Pads		
Rear Master Cylinder		
Rear Brake Lines		
Rear Rotors		

Battery / Electrical System	Pass	Fail
Replace Battery		
Regulator Rectifier		

Headlight	Pass	Fail
Head Light Lens		
High Beam Bulb		
Low Beam Bulb		
Headlight Aim	/	

Turn Signals	Pass	Fail
Turn Signal Operation		

Dashes / Gauges	Pass	Fail
Speedometer / Odometer		
Tachometer		
Indicator / Backlights		

Horns & Switches	Pass	Fail
Horn Operation		
Stop Switch Operation		7
Safety Switch Operation		

Handlebars and Grips	Pass	Fail
Handlebar Operation		Ve
Grips Operation		- made

Wheels / Tires	Pass	Fail
Front Wheel		V
Front Wheel Bearings		
Front tire		
Rear Wheel		
Rear Tire		1811
Rear Wheel Bearings		

Steering / Alignment	Pass	Fail
Headset Bearings		
Steering Operation		

Suspension	Pass	Fail
Fork Seals		
Fork Legs	V ,	
Rear Suspension		

Fuel System	Pass	Fail
Fuel Tank		
Carbs / Injectors	/	

Exhaust System	Pass	Fail
Exhaust Operation		

Cooling System	Pass	Fail
Radiatior operation		COMP
Fan Operation	1	
Hoses, Water Pump, System	/	

Test Ride Notes and Vehicle Information

The bike has a tail tidy, aftermarket full system exhaust, aftermarket rearset, aftermarket levers, steel braided brake lines except rear caliper, aftermarket windscreen, case savers equipped, radiator guards equipped, carbon fiber front and rear fender, carbon fiber frame covers, carbon fiber swingarm covers, carbon fiber gas tank cover, carbon fiber belly pan, aftermarket quickershifter, has been tuned. Black tail fairing is faded, and the frame and swingarm covers are faded,