

# USED BIKES DIRECT

Yamaha

MT10

2021

4156

Service Items	Pass	Fail
Oil / Filter change	✓	
Vehicle Detailed	✓	
Tag "Certified"	✓	
Tag "As Is"		

Chain / Sprockets	Pass	Fail
Chain Condition	✓	
Sprocket Condition	✓	
Belt Drive condition		
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens	✓	
Running Light	✓	
Brake Light	✓	

License Plate	Pass	Fail
LP Bracket	✓	
License Plate Light	✓	

Mirrors	Pass	Fail
Mirrors	✓	

Cables / Controls / Levers	Pass	Fail
Throttle Operation	✓	
Clutch Cable Operation	✓	
All Levers Operation	✓	

Brakes	Pass	Fail
Front Pads	✓	
Front Master Cylinder	✓	
Front Brake Lines	✓	
Front Rotors	✓	
Rear Brake Pads	✓	
Rear Master Cylinder	✓	
Rear Brake Lines	✓	
Rear Rotors	✓	

Battery / Electrical System	Pass	Fail
Replace Battery	✓	
Regulator Rectifier	✓	

Headlight	Pass	Fail
Head Light Lens	✓	
High Beam Bulb	✓	
Low Beam Bulb	✓	
Headlight Aim	✓	

Turn Signals	Pass	Fail
Turn Signal Operation	✓	

Dashes / Gauges	Pass	Fail
Speedometer / Odometer	✓	
Tachometer	✓	
Indicator / Backlights	✓	

Horns & Switches	Pass	Fail
Horn Operation	✓	
Stop Switch Operation	✓	
Safety Switch Operation	✓	

Handlebars and Grips	Pass	Fail
Handlebar Operation	✓	
Grips Operation	✓	

Wheels / Tires	Pass	Fail
Front Wheel	✓	
Front Wheel Bearings	✓	
Front tire	✓	
Rear Wheel	✓	
Rear Tire	✓	
Rear Wheel Bearings	✓	

Steering / Alignment	Pass	Fail
Headset Bearings	✓	
Steering Operation	✓	



Suspension	Pass	Fail
Fork Seals	✓	
Fork Legs	✓	
Rear Suspension	✓	

Fuel System	Pass	Fail
Fuel Tank	✓	
Carbs / Injectors	✓	

Exhaust System	Pass	Fail
Exhaust Operation	✓	

Cooling System	Pass	Fail
Radiator operation	✓	
Fan Operation	✓	
Hoses, Water Pump, System	✓	

#### Test Ride Notes and Vehicle Information

Right fork tube has minor rust pitting  
Exhaust and oil cooler has minor rust and corrosion, bike may have been sitting outside for a while