USEDBIKESDIRECT

Make: Honda **Model:** CBR600RR **Year:** 2022

Stock #: 800361 **Mileage:** 6271

8 Mile Test Ride	Completed
Complete 8 mile test ride	☑

20 Minute Idle	Completed
Complete 20 minute idle	☑

Service Items	Pass	Fail
Oil / Filter Change	☐	☑
Vehicle Detailed	☐	☐
Tag "Certified"	☐	☐
Tag "As Is"	☐	☐

Chain / Sprockets	Pass	Fail
Chain Condition	☑	☐
Chain Adjuster Inspection	☑	☐
Sprocket Condition	☑	☐
Belt Drive Condition	☐	☐
Shaft Drive Condition	☐	☐

Tail Light	Pass	Fail
Lens	☑	☐
Running Light	☑	☐
Brake Light - Front Lever	☑	☐
Brake Light - Rear Pedal	☑	☐

License Plate	Pass	Fail
LP Bracket	☐	☑
License Plate Light	☐	☑

Mirrors	Pass	Fail
Mirrors	☑	☐

Handlebars and Grips	Pass	Fail
Handlebar Operation	☑	☐
Grips Operation	☑	☐

Battery / Electrical System		Pass	Fail
Replace Battery		☑	☐
Regulator Rectifier		☑	☐
Charging System Test	14.2 V	☑	☐

Headlight	Pass	Fail
Head Light Lens	☑	☐
High Beam Bulb	☑	☐
Low Beam Bulb	☑	☐
Headlight Aim	☑	☐

Turn Signals	Pass	Fail
Turn Signal Operation	☑	☐
Turn Signal Condition	☑	☐

Dashes / Gauges	Pass	Fail
Speedometer / Odometer	☑	☐
Tachometer	☑	☐
Indicator / Backlights	☑	☐

Horns & Switches	Pass	Fail
Horn Operation	☑	☐
Stop Switch Operation	☑	☐
Safety Switch Operation	☑	☐

Fuel System	Pass	Fail
Fuel Tank - Inside	☑	☐
Fuel Tank - Outside	☑	☐
Carbs / Injectors	☑	☐

Inspection (continued)

Stock #: 800361 **Mileage:** 6271

Cables / Controls / Levers	Pass	Fail
Throttle Operation	☑	☐
Throttle Cable Free Play	☑	☐
Clutch Cable Operation	☑	☐
Clutch Cable Free Play	☑	☐
Cable Routing	☑	☐
All Levers Operation	☑	☐
Quick Shifter (if equipped)	☐	☐

Brakes			Pass	Fail
Front Pads	90	% life	☑	☐
Front Master Cylinder			☑	☐
Front Brake Lines			☑	☐
Front Rotors			☑	☐
Rear Brake Pads	75	% life	☑	☐
Rear Master Cylinder			☑	☐
Rear Brake Lines			☑	☐
Rear Rotor			☑	☐

Suspension	Pass	Fail
Fork Seals	☑	☐
Fork Dust Covers	☑	☐
Fork Legs	☑	☐
Rear Suspension	☐	☐

Wheels / Tires			Pass	Fail
Front Wheel			☑	☐
Front Wheel Bearings			☑	☐
Front Tire	39/22	date code	☑	☐
Front Tread Depth	4	/32"	☑	☐
Rear Wheel			☑	☐
Rear Tire	39/22	date code	☑	☐
Rear Tread Depth	5	/32"	☑	☐
Rear Wheel Bearing Play			☑	☐

Steering / Alignment	Pass	Fail
Headset Bearings	☑	☐
Steering Operation	☑	☐
Front Steering Alignment	☑	☐

Exhaust System	Pass	Fail
Exhaust Operation	☑	☐

Cooling System	Pass	Fail
Radiator Operation	☑	☐
Fan Operation	☑	☐
Hoses, Water Pump, System	☑	☐

Test Ride Notes and Vehicle Information

Test ride performed as should
Needs an oil change
No other issues found.

Technician: Jacob Wilkerson **Date:** 11/7/26