

# USED BIKES DIRECT

Yamaha

YZFR1

2022

000830

Service Items	Pass	Fail
Oil / Filter change	✓	
Vehicle Detailed	✓	
Tag "Certified"		
Tag "As Is"	✓	

Chain / Sprockets	Pass	Fail
Chain Condition	✓	
Sprocket Condition	✓	
Belt Drive condition		
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens	✓	
Running Light	✓	
Brake Light	✓	

License Plate	Pass	Fail
LP Bracket	✓	
License Plate Light	✓	

Mirrors	Pass	Fail
Mirrors	✓	

Cables / Controls / Levers	Pass	Fail
Throttle Operation	✓	
Clutch Cable Operation	✓	
All Levers Operation	✓	

Brakes	Pass	Fail
Front Pads	✓	
Front Master Cylinder	✓	
Front Brake Lines	✓	
Front Rotors	✓	
Rear Brake Pads	✓	
Rear Master Cylinder	✓	
Rear Brake Lines	✓	
Rear Rotors	✓	

Battery / Electrical System	Pass	Fail
Replace Battery	✓	
Regulator Rectifier	✓	

Headlight	Pass	Fail
Head Light Lens	✓	
High Beam Bulb	✓	
Low Beam Bulb	✓	
Headlight Aim	✓	

Turn Signals	Pass	Fail
Turn Signal Operation	✓	

Dashes / Gauges	Pass	Fail
Speedometer / Odometer	✓	
Tachometer	✓	
Indicator / Backlights	✓	

Horns & Switches	Pass	Fail
Horn Operation	✓	
Stop Switch Operation	✓	
Safety Switch Operation	✓	

Handlebars and Grips	Pass	Fail
Handlebar Operation	✓	
Grips Operation	✓	

Wheels / Tires	Pass	Fail
Front Wheel	✓	
Front Wheel Bearings	✓	
Front tire	✓	
Rear Wheel	✓	
Rear Tire	✓	
Rear Wheel Bearings	✓	

Steering / Alignment	Pass	Fail
Headset Bearings	✓	
Steering Operation	✓	

Suspension	Pass	Fail
Fork Seals	✓	
Fork Legs	✓	
Rear Suspension	✓	

Fuel System	Pass	Fail
Fuel Tank	✓	
Carbs / Injectors	✓	

Exhaust System	Pass	Fail
Exhaust Operation	✓	

Cooling System	Pass	Fail
Radiator operation	✓	
Fan Operation	✓	
Hoses, Water Pump, System	✓	

Test Ride Notes and Vehicle Information
<p>2607 miles          Has NON-OEM body kit          Multiple scuffs &amp; scratches on both wheels          Bike has been down on RH side, possibly both sides          Scuffed RH engine cover          RH side frame and engine mount bolt are scuffed          RH fork upper tube is gouged          Both mirrors are scratched          RH bar end is scratched          LH side of swingarm is scratched          Black residue on RH passenger peg          Rear of passenger seat is scuffed</p>