## **USEDBIKESDIRECT**

Suzuki	GSXR600	2023	100836

Service Items	Pass	Fail
Oil / Filter change		1
Vehicle Detailed		
Tag "Certified"		
Tag "As Is"		

Chain / Sprockets	Pass	Fail
Chain Condition		
Sprocket Condition		
Belt Drive condition	4	
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens		
Running Light		
Brake Light		

License Plate	Pass	Fail
LP Bracket		
License Plate Light	<b></b>	

Mirrors	Pass	Fail
Mirrors		

Cables / Controls / Levers	Pass	Fail
Throttle Operation		
Clutch Cable Operation		
All Levers Operation		

Brakes	Pass	Fail
Front Pads		
Front Master Cylinder		
Front Brake Lines		\
Front Rotors		
Rear Brake Pads		
Rear Master Cylinder		
Rear Brake Lines		
Rear Rotors		

Battery / Electrical System	Pass	Fail
Replace Battery		
Regulator Rectifier		

Headlight	Pass	Fail
Head Light Lens		
High Beam Bulb		
Low Beam Bulb		
Headlight Aim		

Turn Signals	Pass	Fail
Turn Signal Operation		

Dashes / Gauges	Pass	Fail
Speedometer / Odometer		
Tachometer		
Indicator / Backlights		

Horns & Switches	Pass	Fail
Horn Operation		
Stop Switch Operation		
Safety Switch Operation		

Handlebars and Grips	Pass	Fail
Handlebar Operation		
Grips Operation		- ( and )

Wheels / Tires	Pass	Fail	
Front Wheel			
Front Wheel Bearings			
Front tire	<b>-</b>		
Rear Wheel			
Rear Tire			
Rear Wheel Bearings			

Steering / Alignment	Pass	Fail	
Headset Bearings			
Steering Operation			

Suspension	Pass	Fail
Fork Seals		
Fork Legs	<b>V</b> ,	
Rear Suspension		

Fuel System	Pass	Fail	
Fuel Tank			
Carbs / Injectors			

<b>Exhaust System</b>	Pass Fail			
Exhaust Operation				

<b>Cooling System</b>	Pass	Fail
Radiatior operation		(0)
Fan Operation	<b>1</b>	
Hoses, Water Pump, System	<b>/</b>	

Test	Ride	Notes	and	Vehicl	e Info	rmation
	IXIU		211111	v enici	е ини	, , , , , , , , , , , , , , , , , , , ,

Windshield and front fairing are "shaved" down Holes in fairings where frame sliders used to be