USEDBIKESDIRECT

Kawasa	/ 1
KUWUSU	N

Ninja 500 KRT

Service Items	Pass	Fail
Oil / Filter change		
Vehicle Detailed		
Tag "Certified"		
Tag "As Is"	/	

Chain / Sprockets	Pass	Fail
Chain Condition		
Sprocket Condition		
Belt Drive condition	4	
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens		
Running Light		
Brake Light		

License Plate	Pass	Fail
LP Bracket		
License Plate Light		

Mirrors	Pass	Fail
Mirrors		

Cables / Controls / Levers	Pass	Fail
Throttle Operation		
Clutch Cable Operation		
All Levers Operation		

Brakes	Pass	Fail
Front Pads		
Front Master Cylinder		
Front Brake Lines		\
Front Rotors		
Rear Brake Pads		
Rear Master Cylinder		
Rear Brake Lines		
Rear Rotors		

2024

A13609

Battery / Electrical System	Pass	Fail
Replace Battery		
Regulator Rectifier		

Headlight	Pass	Fail
Head Light Lens		
High Beam Bulb		
Low Beam Bulb		
Headlight Aim	/	

Turn Signals	Pass	Fail
Turn Signal Operation		

Dashes / Gauges	Pass	Fail
Speedometer / Odometer		
Tachometer		
Indicator / Backlights		

Horns & Switches	Pass	Fail
Horn Operation		
Stop Switch Operation		7
Safety Switch Operation		

Handlebars and Grips	Pass	Fail
Handlebar Operation		
Grips Operation		- (a mark

Wheels / Tires	Pass	Fail
Front Wheel		V SAIS
Front Wheel Bearings		
Front tire		
Rear Wheel		
Rear Tire		2 /
Rear Wheel Bearings		5///

Steering / Alignment	Pass	Fail
Headset Bearings		
Steering Operation		

Suspension	Pass	Fail
Fork Seals		
Fork Legs	V ,	
Rear Suspension		

Fuel System	Pass	Fail
Fuel Tank		
Carbs / Injectors		

Exhaust System	Pass	Fail
Exhaust Operation		

Cooling System	Pass	Fail
Radiatior operation		COM
Fan Operation		* ***
Hoses, Water Pump, System	/	

Test Ride Notes and Vehicle Information

13,278 miles
Key fob case is damaged
Bike is lowered
Wheels are painted flat black that is wearing off and the original green is coming thru in some spots
Aftermarket exhaust is damaged and missing some mounting hardware