## **USEDBIKESDIRECT**

Kawasa	<b>7</b> 1
KUWUSU	NI

## Vulcan S Cafe

Service Items	Pass	Fail
Oil / Filter change		1
Vehicle Detailed		
Tag "Certified"		
Tag "As Is"		

Chain / Sprockets	Pass	Fail
Chain Condition		
Sprocket Condition		
Belt Drive condition	4	
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens		
Running Light		
Brake Light	<b>/</b>	

License Plate	Pass	Fail
LP Bracket		
License Plate Light		

Mirrors	Pass	Fail
Mirrors		

Cables / Controls / Levers	Pass	Fail
Throttle Operation		
Clutch Cable Operation		
All Levers Operation	<b> </b>	

Brakes	Pass	Fail
Front Pads		
Front Master Cylinder		
Front Brake Lines		
Front Rotors		
Rear Brake Pads		
Rear Master Cylinder		
Rear Brake Lines		
Rear Rotors		

## 2023

## A01006

Battery / Electrical System	Pass	Fail
Replace Battery		
Regulator Rectifier	<b>/</b>	

Headlight	Pass	Fail
Head Light Lens		
High Beam Bulb		
Low Beam Bulb		
Headlight Aim	<b>/</b>	

Turn Signals	Pass	Fail
Turn Signal Operation	<b>/</b>	

Dashes / Gauges	Pass	Fail
Speedometer / Odometer		
Tachometer	<b>/</b>	
Indicator / Backlights	<b>/</b>	

Horns & Switches	Pass	Fail
Horn Operation		
Stop Switch Operation		
Safety Switch Operation	<b>/</b>	

Handlebars and Grips	Pass	Fail
Handlebar Operation		Ve
Grips Operation		A STATE OF THE STA

Wheels / Tires	Pass,	Fail
Front Wheel		V JAS
Front Wheel Bearings	<b>Y</b> .	
Front tire		
Rear Wheel		
Rear Tire		2//
Rear Wheel Bearings		5/

Steering / Alignment	Pass	Fail
Headset Bearings		
Steering Operation		

Suspension	Pass	Fail
Fork Seals		
Fork Legs	<b>_</b>	
Rear Suspension		

Fuel System	Pass	Fail
Fuel Tank		
Carbs / Injectors		

<b>Exhaust System</b>	Pass	Fail
Exhaust Operation	<b>/</b>	

<b>Cooling System</b>	Pass	Fail
Radiatior operation		COME
Fan Operation		
Hoses, Water Pump, System	<b>✓</b>	

Test Ride Notes and Vehicle Information			
4344 miles Tires are 50% worn Missing bar ends			