## **USEDBIKESDIRECT**

Service Items	Pass	Fail
Oil / Filter change		
Vehicle Detailed		
Tag "Certified"		
Tag "As Is"	<b>/</b>	

Concourse

Kawasaki

Chain / Sprockets	Pass	Fail
Chain Condition		
Sprocket Condition		
Belt Drive condition	4	
Shaft Drive Condition		

Tail Light	Pass	Fail
Lens		
Running Light		
Brake Light		

License Plate	Pass	Fail
LP Bracket		
License Plate Light		

Mirrors	Pass	Fail
Mirrors		

Cables / Controls / Levers	Pass	Fail
Throttle Operation		
Clutch Cable Operation		
All Levers Operation		

Brakes	Pass	Fail
Front Pads		
Front Master Cylinder		
Front Brake Lines		
Front Rotors		
Rear Brake Pads		
Rear Master Cylinder		
Rear Brake Lines		
Rear Rotors		

## 2014 024021

Battery / Electrical System	Pass	Fail
Replace Battery		
Regulator Rectifier		

Headlight	Pass	Fail
Head Light Lens		
High Beam Bulb		
Low Beam Bulb		
Headlight Aim	<b>/</b>	

Turn Signals	Pass	Fail
Turn Signal Operation		

Dashes / Gauges	Pass	Fail
Speedometer / Odometer		
Tachometer		
Indicator / Backlights		(0)

Horns & Switches	Pass	Fail
Horn Operation		
Stop Switch Operation		
Safety Switch Operation		

Handlebars and Grips	Pass	Fail
Handlebar Operation		Ve
Grips Operation		- made

Wheels / Tires	Pass	Fail
Front Wheel		V Sale
Front Wheel Bearings		
Front tire		
Rear Wheel		
Rear Tire		R
Rear Wheel Bearings		

Steering / Alignment	Pass	Fail
Headset Bearings	<b>V</b> .	
Steering Operation		

Suspension	Pass	Fail
Fork Seals		
Fork Legs	<b>V</b> ,	
Rear Suspension		

Fuel System	Pass	Fail
Fuel Tank		
Carbs / Injectors		1

Exhaust System	Pass	Fail
Exhaust Operation		

<b>Cooling System</b>	Pass	Fail
Radiatior operation		) COM
Fan Operation		* ***
Hoses, Water Pump, System	<b>/</b>	

## **Test Ride Notes and Vehicle Information**

Coolant has been flushed
Rear wheel scraped
Slave cylinder leaking Paint peeling
Rusted bolts all over bike
Peeling metal bars around rear compartment
Fuel tank hard to open due to corrosion
Unit sat outside for sometime very dirty underneath seat and engine bay
Body has scratches and scuffs all over
Rear cargo scratched and scuffed